


In-line Relay Interface

(12 volt model)



- Operate traps using longer and/or thinner release cables.
- Operate 110 volt traps (110 volts on the release cables) with more effective electrical safety as the release cable now carries extra low voltages.
- Interface 110 volt traps, as above, with Claymate systems.
- Interface Claymate with the (very) few traps that do not provide sufficient power to Claymate.
- Increase trap battery life as there is now no voltage loss in the release circuit.

How to connect the Interface...

The Interface requires an external power supply. This can usually be derived from the trap provided that the voltage does not exceed 15 volts AC for this 12 volt model. If in doubt... measure using a meter. The interface is a trap modification and should be mounted such that the interface and trap are moved as a single item.

- Connect a power supply to the terminals marked 12v and 0v. The unit is polarity protected.
- Shorting the 'claymate' pins will energise the relay.
- Connect Claymate or alternative release system to the 'claymate' pins and check operation.
- Connect the trap release wires from the trap to the 'Trap' terminals and check operation.
- Secure the interface, having wrapped it in insulating material, out of harms way.

The unit is not supplied wired or boxed due the numerous installation situations where an enclosure, if supplied, would be too large to 'hide' within the constraints of the trap wiring enclosure. Boxed and pre wired units can be supplied at additional cost.

SAFETY STATEMENT

Neither Claymate Trap Control Systems, BLN Technical Services or agents of BLN will be responsible for accidents or injury or loss caused by operation of traps or associated equipment under the control of any Claymate System whether the operation of such equipment is desirable or not; is caused by operation of any equipment when it is unsafe to do so, or under any fault condition of any equipment howsoever caused.

BLN Technical Services

E-mail rick@blntechnicalsvcs.com

Claymate Trap Control Systems

E-mail sales@claymate.co.uk

Silver Willows

The Croft

Bures

Suffolk

CO8 5JL

UK

Tel +44(0) 1787-228143 Fax +44(0) 1787-227503 WEB www.claymate.co.uk